1

# Billing Code 9110-12-P

# DEPARTMENT OF HOMELAND SECURITY

**Federal Emergency Management Agency** 

44 CFR Part 67

[Docket ID FEMA-2014-0002; Internal Agency Docket No. FEMA-B-1175]

**Proposed Flood Elevation Determinations** 

**AGENCY:** Federal Emergency Management Agency, DHS.

**ACTION:** Proposed rule; correction.

SUMMARY: On February 16, 2011, the Federal Emergency Management Agency (FEMA) published in the <u>Federal Register</u> a proposed rule that contained an erroneous table. This document provides corrections to that table, to be used in lieu of the information published on February 16, 2011. The table provided here represents the flooding sources, location of referenced elevations, effective and modified elevations, and communities affected for Montgomery County, Pennsylvania (All Jurisdictions).

DATES: Comments are to be submitted on or before [INSERT DATE 90 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

ADDRESSES: You may submit comments, identified by Docket No. FEMA-B-1175, to Luis Rodriguez, Chief, Engineering Management Branch, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street SW., Washington, DC 20472, (202) 646-4064 or (e-mail) <a href="Luis.Rodriguez3@fema.dhs.gov"><u>Luis.Rodriguez3@fema.dhs.gov.</u></a>.

FOR FURTHER INFORMATION CONTACT: Luis Rodriguez, Chief, Engineering Management Branch, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street SW., Washington, DC 20472, (202) 646-

4064 or (e-mail) Luis.Rodriguez3@fema.dhs.gov.

**SUPPLEMENTARY INFORMATION:** FEMA publishes proposed determinations of Base (1% annual-chance) Flood Elevations (BFEs) and modified BFEs for communities participating in the National Flood Insurance Program (NFIP), in accordance with section 110 of the Flood Disaster Protection Act of 1973, 42 U.S.C. 4104, and 44 CFR 67.4(a).

These proposed BFEs and modified BFEs, together with the floodplain management criteria required by 44 CFR 60.3, are minimum requirements. They should not be construed to mean that the community must change any existing ordinances that are more stringent in their floodplain management requirements. The community may at any time enact stricter requirements of its own or pursuant to policies established by other Federal, State, or regional entities. These proposed elevations are used to meet the floodplain management requirements of the NFIP and also are used to calculate the appropriate flood insurance premium rates for new buildings built after these elevations are made final, and for the contents in those buildings.

In the proposed rule published at 76 FR 8982-8984, in the February 16, 2011, issue of the Federal Register, FEMA published a table under the authority of 44 CFR 67.4. The table, entitled "Montgomery County, Pennsylvania all Jurisdictions" addressed the flooding sources: Blair Mill Run, Blair Mill Run Tributary, Huntingdon Valley Creek, Meadow Brook, Pennypack Creek, Pennypack Creek Branch, Pennypack Creek Tributary No. 1, Pine Run, Rapp Run, Sandy Run, Sandy Run Tributary No. 1, Sandy Run Tributary No. 1a (downstream), Sandy Run Tributary No. 1a (upstream), Southampton Creek, Tributary No. 2 to Pine Run, and War Memorial Creek. That table contained inaccurate information as to the location of referenced elevation, effective and

modified elevation in feet, and/or communities affected for the flooding sources Sandy Run, Sandy Run Tributary No. 1 and Sandy Run Tributary No. 1a (downstream). In addition, the proposed modifications listed for Sandy Run Tributary No. 1a (upstream) has been removed from the table. FEMA is no longer proposing any flood elevation determination changes along Sandy Run Tributary No. 1a (upstream) as identified in the above-referenced rulemaking publication. In this document, FEMA is publishing a table containing the accurate information, to address these prior errors. The information provided below should be used in lieu of that previously published.

# Correction

In Proposed rule FR Doc. 2011-3420, beginning on page 8978 in the issue of February 16, 2011, make the following correction. On pages 8982-8984, correct the Montgomery County, Pennsylvania table as follows:

Montgomery County, Pennsylvania (All Jurisdictions)					
_			on in feet		
		(NGVD)			
		+Elevation in feet			
		(NAVD)			
		#Depth in feet			
		above ground			
		^Elevation in			
		meters (MSL)			
Flooding source(s)		Effective	Modified	Communities affected	
Blair Mill Run	At the Pennypack Creek confluence	+212	+211	Borough of Hatboro,	
	At the downstream side of County Line	+259	+261	Township of Horsham,	
	Road			Township of Upper	
				Moreland	
Blair Mill Run	At the upstream side of West Monument	+227	+228	Borough of Hatboro	
Tributary	Avenue				
	At the downstream side of East County	+247	+252		
	Line Road				
Huntingdon	Approximately 800 feet downstream of	+119	+120	Borough of Bryn	
Valley Creek	Red Lion Road			Athyn, Township of	
	Approximately 0.9 mile upstream of	+264	+267	Lower Moreland	
	Byberry Road				
Meadow Brook	At the Pennypack Creek confluence	+115	+118	Township of Abington,	
	Approximately 1,000 feet upstream of	None	+287	Township of Lower	
	the most upstream State Highway 2017			Moreland	

	1	ı	Ì	4
Pennypack Creek	crossing Approximately 1,200 feet downstream of Moredon Road	+99	+100	Borough of Bryn Athyn, Borough of
	Approximately 1.0 mile upstream of Mann Road	None	+359	Hatboro, Township of Abington, Township of Horsham, Township of Lower Moreland, Township of Upper Dublin, Township of Upper Moreland
Pennypack Creek Branch	Approximately 400 feet downstream of Witmer Road	+299	+298	Township of Horsham
	Approximately 0.7 mile upstream of Witmer Road	None	+362	
Pennypack Creek	At the Pennypack Creek confluence	+198	+204	Borough of Hatboro,
Tributary No. 1	Approximately 0.7 mile upstream of Dresher Road	None	+341	Township of Horsham, Township of Upper Moreland
Pine Run	At the upstream side of State Highway 309	+171	+176	Township of Upper Dublin
	Approximately 800 feet upstream of Dreshertown Road	+231	+239	
Rapp Run	At the Pine Run confluence	+177	+183	Township of Upper
	Approximately 0.5 mile upstream of the most upstream Lexington Drive crossing	+351	+355	Dublin
Sandy Run	Approximately 300 feet downstream of Bethlehem Pike	None	+159	Township of Abington, Township of
	Approximately 1,400 feet upstream of Roberta Avenue	None	+339	Springfield, Township of Upper Dublin, Township of Whitemarsh
Sandy Run Tributary No. 1	Approximately 150 feet upstream of Johnston Avenue	+237	+236	Township of Abington
	Approximately 2,000 feet upstream of Johnston Avenue	None	+258	
Sandy Run Tributary No. 1a	Approximately 250 feet upstream of Fernwood Avenue	+238	+237	Township of Abington
(downstream)	Approximately 1,100 feet upstream of Fernwood Avenue	None	+243	
Southampton	At the Pennypack Creek confluence	+176	+177	Borough of Bryn
Creek	At the downstream side of County Line Road	+184	+187	Athyn, Township of Lower Moreland, Township of Upper Moreland
Tributary No. 2 to Pine Run	At the Pine Run confluence Approximately 1.1 miles upstream of	None None	+202 +232	Township of Upper Dublin
117 N	the Pine Run confluence	1100	. 100	T 1: 011
War Memorial Creek	At the Pennypack Creek confluence Approximately 700 feet upstream of Mineral Avenue	+189 +265	+190 +267	Township of Upper Moreland
*National Geodetic				I

<sup>\*</sup>National Geodetic Vertical Datum.

<sup>+</sup>North American Vertical Datum.

+Depth in feet above ground.

^Mean Sea Level, rounded to the nearest 0.1 meter.

\*\* BFEs to be changed include the listed downstream and upstream BFEs, and include BFEs located on the stream reach between the referenced locations above. Please refer to the revised Flood Insurance Rate Maps (FIRMs) located at the community map repository (see below) for exact locations of all BFEs to be changed. Revised FIRMs may also be viewed online at http://www.fema.gov/preliminaryfloodhazarddata.

Send comments to Luis Rodriguez, Chief, Engineering Management Branch, Federal Insurance and Mitigation Administration, Federal Emergency Management Agency, 500 C Street SW., Washington, DC 20472.

#### ADDRESSES:

# **Borough of Bryn Athyn**

Maps are available for inspection at the Borough Hall, 2835 Buck Road, Bryn Athyn, PA 19009

# **Borough of Hatboro**

Maps are available for inspection at the Borough Hall, 414 South York Road, Hatboro, PA 19040

#### **Township of Abington**

Maps are available for inspection at the Township Building, Engineer's Office, 1176 Old York Road, Abington, PA 19001

# **Township of Horsham**

Maps are available for inspection at the Township Municipal Building, 1025 Horsham Road, Horsham, PA 19044

### **Township of Lower Moreland**

Maps are available for inspection at the Lower Moreland Municipal Building, 640 Red Lion Road, Huntingdon Valley, PA 19006

# **Township of Springfield**

Maps are available for inspection at the Springfield Township Municipal Building, 1510 Paper Mill Road, Wyndmoor, PA 19038

# **Township of Upper Dublin**

Maps are available for inspection at the Upper Dublin Municipal Hall, 801 Loch Alsh Avenue, Fort Washington, PA 19034

### **Township of Upper Moreland**

Maps are available for inspection at the Upper Moreland Township Building, 117 Park Avenue, Willow Grove, PA 19090

# **Township of Whitemarsh**

Maps are available for inspection at the Whitemarsh Township Administrative Building, 616 Germantown Pike, Lafayette Hill, PA 19444

(Catalog of Federal Domestic Assistance No. 97.022, "Flood Insurance.")

	Date: July 11, 2014_
Roy E. Wright,	

Deputy Associate Administrator for Mitigation,

Department of Homeland Security,

Federal Emergency Management Agency.

[FR Doc. 2014-18101 Filed 08/07/2014 at 8:45 am; Publication Date: 08/08/2014]